

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



ON REPORT

Michael O. Leavitt Governor Lowell P. Braxton Division Director PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

1594 West North Temple, Suite 1210

Partial: XXX Complete: Exploration: Inspection Date & Time: 1/29/99 / 7:00a.m.-9:00a.m.

Date of Last Inspection: 12/22/98

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019						
Permittee and/or Operator's Name: Andalex Resources, Inc.						
Business Address: P.O. Box 902, Price, Utah 84501						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Mike Glasson						
State Officials(s): Stephen J. Demczak Federal Official(s): None						
Weather Conditions: Clear, 6" snow, 20's						
Existing Acreage: Permitted-5063 Disturbed-34 Regraded-0 Seeded-0 Bonded-34						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3. 4.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE:	EVALUATED [XX] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX] [XX] [XX]	NOV/ENF
a.	DIVERSIONS	[XX]		[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	\Box	[XX]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	\Box	[XX]	\Box
d.	WATER MONITORING	Ц	Ц	Ц	Ц
e. 5.	EFFLUENT LIMITATIONS EXPLOSIVES		Ц		Ļļ
5. 6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		Ӊ		⊢
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[<u>]</u> [XX]	Η		Ӊ
8.	NONCOAL WASTE		Η		片
9.	PROTECTION OF FISH, WILDLIFE AND	IXXI	ш	IXXI	ш.
	RELATED ENVIRONMENTAL VALUES	ſ1	1.1	[]	[]
10.	SLIDES AND OTHER DAMAGE	Ħ	Ħ	Ħ	Ħ
11.	CONTEMPORANEOUS RECLAMATION	Ħ	ii	П	ī
12.	BACKFILLING AND GRADING		\Box		\Box
13.	REVEGETATION	□	Π		\Box
14.	SUBSIDENCE CONTROL	$\overline{[XX]}$	\Box	$\overline{[XX]}$	\Box
15.	CESSATION OF OPERATIONS		\Box	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	Ц	Ц	\Box
b.	DRAINAGE CONTROLS	Ц	ĮЦ	Ц	Ц
17.	OTHER TRANSPORTATION FACILITIES	LI.	Ц		Ļļ
18. 19.	SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4th Quarter April May 1		H	[XX]	닞
19. 20.	AVS CHECK (4th Quarter-April, May, June)(date) AIR QUALITY PERMIT	Ц	H	니	Η
21.	BONDING & INSURANCE	H	H	片	난
~ · ·	BONDING & INSURANCE	\sqcup	↓ ↓	↓ ↓	

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 1/29/99

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT-

There have been no violations issued and there are no outstanding violations. The permittee has submitted an incidental boundary change two weeks ago to the Division. This incidental boundary will be 140 acres or 2.6% of the permit area. The 140 acres is fee ground. It is planned to be reviewed by February 15, 1999. The plan is being reviewed by both PFO and SLO.

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas. The permittee has stream buffer zones signs placed within the disturbed area. Topsoil ID signs are located on the topsoil piles as required in the R645 Coal Rules. There are stream buffer zone signs posted throughout the mine property. The topsoil signs are posted on the topsoil piles as required.

3. TOPSOIL -

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by berms and/or vegetation.

4A. DIVERSIONS -

The diversions were spot-checked and found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules performance standards. Sediment has recently been cleaned out of several diversions.

4B. SEDIMENT PONDS -

The sediment pond was not discharging during the inspection and could potentially discharge in the near future either from the mine or pond itself. The ponds did contain water. There were no signs of any hazardous conditions occurring to the sediment ponds during the inspection.

The Annual sediment pond inspection was made on November 9, 1998 with no hazardous conditions being reported. Sediment pond E has .04 acre feet before clean out. Centennial Project has two sediment ponds and one sediment basin consisting of four cells.

4C. OTHER SEDIMENT CONTROL MEASURES -

Centennial Project uses straw bales and berms as its alternate sediment control measures. These areas were spot-inspected and complied with the R645 Coal Rules. Work on the silt fences was being performed during the inspection. Silt fences have recently been cleaned out.

5. EXPLOSIVES -

There are explosives boxes on the property which are located on the upper end of the disturbed area. There were no explosives used during fourth quarter.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 1/29/99

(Comments are Numbered to Correspond with Topics Listed Above)

7. REFUSE PILE -

There are no refuse piles located at the Andalex Mines; all material is taken to Wildcat Loadout.

8. NON-COAL WASTE -

The area was clear of non-coal waste material. This material is being stored in dumpsters.

14. SUBSIDENCE -

The 1998 subsidence report was reviewed and is P.E. certified. The subsidence survey stated that there was no horizontal or vertical movement.

18. SUPPORT FACILITIES -

During the field inspection, no new structures were added for fourth quarter.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: January 28, 1999

Inspector's Signature:

#39